

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	1333	331/117R.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/05/21 10:02			
2	BRS	L2	308	331/117fe.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/05/21 10:02			
3	BRS	L4	806	331/177v.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/05/21 10:03			
4	BRS	L5	440	331/36c.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/05/21 10:03			
5	BRS	L6	753	331/179.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/05/21 10:03			
6	BRS	L7	1204	Ic near oscillator	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/05/21 10:04			
7	BRS	L8	30904	switch\$3 near capacit\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/05/21 10:05			
8	BRS	L9	119	7 and 8	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/05/21 10:05			